



Aeroflex (MACOM Technology Solutions)

MACP-011034

Nomor bagian:	MACP-011034
Pabrikan / Merek:	Aeroflex (MACOM Technology Solutions)
Deskripsi Produk:	RF DIR COUPLER 5MHZ-1.2GHZ 6SMD
Lembar data:	MACP-011034.pdf
Status RoHS:	Bebas timah / Sesuai RoHS
Kondisi stok:	34659 pcs stock
Kirim Dari:	Hongkong
Cara pengiriman:	DHL/Fedex/TNT/UPS/EMS

Solutions



Gambar bisa berupa representasi. Lihat spesifikasi untuk detail produk.

PERMINTAAN KUTIPAN

Spesifikasi MACP-011034

NOMOR BAGIAN	MACP-011034
PABRIKAN	Aeroflex (MACOM Technology Solutions)
DESKRIPSI	RF DIR COUPLER 5MHZ-1.2GHZ 6SMD
MEMIMPIN STATUS BEBAS / STATUS ROHS	Bebas timah / Sesuai RoHS
JUMLAH YANG TERSEDIA	34659 pcs
LEMBARAN DATA	MACP-011034.pdf
PAKET PERANGKAT PEMASOK	6-SMD
SERI	-
MENGEMBALIKAN KERUGIAN	-20dB
LISTRİK - MAX	0.5W
PENGEMASAN	Cut Tape (CT)
PAKET / CASE	6-SMD
NAMA LAIN	1465-1807-1
MOISTURE SENSITIVITY LEVEL (MSL)	1 (Unlimited)
STATUS GRATIS MEMIMPIN / STATUS ROHS	Lead free / RoHS Compliant
ISOLASI	30dB
PENYISIPAN RUGI	-
FREKUENSI	5MHz ~ 1.2GHz
DETIL DESKRIPSI	RF Directional Coupler General Purpose 5MHz ~ 1.2GHz 10dB 0.5W 6-SMD
COUPLING FACTOR	10dB
COUPLER JENIS	Standard
APLIKASI	General Purpose

Tag terkait

Aeroflex (MACOM Technology Solutions) MACP-011034	Distributor MACP-011034	Pemasok MACP-011034
Harga MACP-011034	Gambar MACP-011034	Gambar MACP-011034
Lembar Data PDF MACP-011034	MACP-011034 Unduh Lembar Data	Lembar Data MACP-011034
Stok MACP-011034	Beli MACP-011034	Beli Aeroflex (MACOM Technology Solutions) MACP-011034
Aeroflex (MACOM Technology Solutions) MACP-011034	Pemasok Aeroflex (MACOM Technology Solutions)	Distributor Aeroflex (MACOM Technology Solutions)
Aeroflex (MACOM Technology Solutions) MACP-011034	Aeroflex Circuit Technology MACP-011034	Aeroflex MACP-011034
Aeroflex (MACOM Technology Solutions) MACP-011034	Aeroflex Metelics, Division of MACOM MACP-011034	M/A-Com Technology Solutions MACP-011034
Metelics (MACOM Technology Solutions) MACP-011034	MACOM Technology Solutions MACP-011034	

Produk-produk terkait

<p>MACP-011032 Produsen: Aeroflex (MACOM Technology Solutions) Deskripsi: RF DIR COUPLER 5MHZ-1.2GHZ 6SMD Persediaan: 33983 pcs</p> <p>RFQ</p>	<p>MACP-011036 Produsen: Aeroflex (MACOM Technology Solutions) Deskripsi: RF DIR COUPLER 5MHZ-1.2GHZ 6SMD Persediaan: 4034 pcs</p> <p>RFQ</p>
<p>MACP-010563-TR1000 Produsen: Aeroflex (MACOM Technology Solutions) Deskripsi: RF DIR COUPLER 10GHZ-30GHZ 6TDFN Persediaan: 4446 pcs</p> <p>RFQ</p>	<p>MACPCT0030 Produsen: Aeroflex (MACOM Technology Solutions) Deskripsi: RF DIR COUPLER 5MHZ-1.2GHZ 6SMD Persediaan: 27402 pcs</p> <p>RFQ</p>
<p>MACP-011015 Produsen: Aeroflex (MACOM Technology Solutions) Deskripsi: RF DIR COUPLER 40MHZ-1.25GHZ 5SMD Persediaan: 24969 pcs</p> <p>RFQ</p>	<p>MACP-011035 Produsen: Aeroflex (MACOM Technology Solutions) Deskripsi: RF DIR COUPLER 5MHZ-1.2GHZ 6SMD Persediaan: 31816 pcs</p> <p>RFQ</p>
<p>MACP-010563-001SMB Produsen: Aeroflex (MACOM Technology Solutions) Deskripsi: EVAL BOARD FOR MACP-010563-TR100 Persediaan: 4608 pcs</p> <p>RFQ</p>	<p>MACP-011038 Produsen: Aeroflex (MACOM Technology Solutions) Deskripsi: RF DIR COUPLER 5MHZ-1.2GHZ 6SMD Persediaan: 5028 pcs</p> <p>RFQ</p>
<p>MACP-011010 Produsen: Aeroflex (MACOM Technology Solutions) Deskripsi: RF DIR COUPLER 5MHZ-1.2GHZ 6SMD Persediaan: 69745 pcs</p> <p>RFQ</p>	<p>MACP-011033 Produsen: Aeroflex (MACOM Technology Solutions) Deskripsi: RF DIR COUPLER 5MHZ-1.2GHZ 6SMD Persediaan: 34032 pcs</p> <p>RFQ</p>
<p>MACP-011013 Produsen: Aeroflex (MACOM Technology Solutions) Deskripsi: RF DIR COUPLER 5MHZ-1.5GHZ 6SMD Persediaan: 75305 pcs</p> <p>RFQ</p>	<p>MACP-011014 Produsen: Aeroflex (MACOM Technology Solutions) Deskripsi: RF DIR COUPLER 5MHZ-1.5GHZ 6SMD Persediaan: 34558 pcs</p> <p>RFQ</p>

