



Aeroflex (MACOM Technology Solutions)

MACP-010507-CH0160

| | |
|-------------------|--|
| Nomor bagian: | MACP-010507-CH0160 |
| Pabrikan / Merek: | Aeroflex (MACOM Technology Solutions) |
| Deskripsi Produk: | RF DIR COUPLER 5MHZ-300MHZ 5SMD |
| Lembar data: | MACP-010507-CH0160.pdf |
| Status RoHs: | Bebas timah / Sesuai RoHS |
| Kondisi stok: | 75562 pcs stock |
| Kirim Dari: | Hongkong |
| Cara pengiriman: | DHL/Fedex/TNT/UPS/EMS |

PERMINTAAN KUTIPAN

Solutions



Gambar bisa berupa representasi. Lihat spesifikasi untuk detail produk.

Spesifikasi MACP-010507-CH0160

| | |
|--------------------------------------|--|
| NOMOR BAGIAN | MACP-010507-CH0160 |
| PABRIKAN | Aeroflex (MACOM Technology Solutions) |
| DESKRIPSI | RF DIR COUPLER 5MHZ-300MHZ 5SMD |
| MEMIMPIN STATUS BEBAS / STATUS ROHS | Bebas timah / Sesuai RoHS |
| JUMLAH YANG TERSEDIA | 75562 pcs |
| LEMBARAN DATA | MACP-010507-CH0160.pdf |
| PAKET PERANGKAT PEMASOK | 5-SMD |
| SERI | - |
| MENGEMBALIKAN KERUGIAN | 31dB |
| LISTRİK - MAX | 500mW |
| PENGEMASAN | Tape & Reel (TR) |
| PAKET / CASE | 5-SMD Module |
| NAMA LAIN | 1465-1718-2 |
| MOISTURE SENSITIVITY LEVEL (MSL) | 1 (Unlimited) |
| STATUS GRATIS MEMIMPIN / STATUS ROHS | Lead free / RoHS Compliant |
| ISOLASI | - |
| PENYISIPAN RUGI | 0.4dB |
| FREKUENSI | 5MHz ~ 300MHz |
| DETIL DESKRIPSI | RF Directional Coupler General Purpose 5MHz ~ 300MHz 17dB 500mW 5-SMD Module |
| COUPLING FACTOR | 17dB |
| COUPLER JENIS | Standard |
| APLIKASI | General Purpose |

Tag terkait

| | | |
|--|---|---|
| Aeroflex (MACOM Technology Solutions) MACP-010507-CH0160 | Distributor MACP-010507-CH0160 | Pemasok MACP-010507-CH0160 |
| Harga MACP-010507-CH0160 | Gambar MACP-010507-CH0160 | Gambar MACP-010507-CH0160 |
| Lembar Data PDF MACP-010507-CH0160 | MACP-010507-CH0160 Unduh Lembar Data | Lembar Data MACP-010507-CH0160 |
| Stok MACP-010507-CH0160 | Beli MACP-010507-CH0160 | Beli Aeroflex (MACOM Technology Solutions) MACP-010507-CH0160 |
| Aeroflex (MACOM Technology Solutions) MACP-010507-CH0160 | Pemasok Aeroflex (MACOM Technology Solutions) | Distributor Aeroflex (MACOM Technology Solutions) |
| Aeroflex (MACOM Technology Solutions) MACP-010507-CH0160 | Aeroflex Circuit Technology MACP-010507-CH0160 | Aeroflex MACP-010507-CH0160 |
| Aeroflex (MACOM Technology Solutions) MACP-010507-CH0160 | Aeroflex Metelics, Division of MACOM MACP-010507-CH0160 | M/A-Com Technology Solutions MACP-010507-CH0160 |
| Metelics (MACOM Technology Solutions) MACP-010507-CH0160 | MACOM Technology Solutions MACP-010507-CH0160 | |

Produk-produk terkait

| | |
|---|--|
| <p>MACP-009730-C60370 Produsen: Aeroflex (MACOM Technology Solutions) Deskripsi: RF DIR COUPLER 5MHZ-1.2GHZ MOD Persediaan: 68058 pcs RFQ</p> | <p>MACP-010561-TR1000 Produsen: Aeroflex (MACOM Technology Solutions) Deskripsi: RF DIR COUPLER 2GHZ-6GHZ 6DFN Persediaan: 4662 pcs RFQ</p> |
| <p>MACP-010562-000000 Produsen: Aeroflex (MACOM Technology Solutions) Deskripsi: RF DIR COUPLER 6GHZ-18GHZ 6TDFN Persediaan: 4595 pcs RFQ</p> | <p>MACP-010414-CA0370 Produsen: Aeroflex (MACOM Technology Solutions) Deskripsi: RF DIR COUPLER 5MHZ-1.2GHZ 6SMD Persediaan: 103049 pcs RFQ</p> |
| <p>MACP-009596-CA01TB Produsen: Aeroflex (MACOM Technology Solutions) Deskripsi: EVAL BOARD FOR MACP-009596-CA016 Persediaan: 485 pcs RFQ</p> | <p>MACP-009596-CA0160 Produsen: Aeroflex (MACOM Technology Solutions) Deskripsi: RF DIR COUPLER 5MHZ-1GHZ SM22 Persediaan: 27221 pcs RFQ</p> |
| <p>MACP-009011-C80370 Produsen: Aeroflex (MACOM Technology Solutions) Deskripsi: RF DIR COUPLER 5MHZ-1.2GHZ 6SMD Persediaan: 29238 pcs RFQ</p> | <p>MACP-010562-TR1000 Produsen: Aeroflex (MACOM Technology Solutions) Deskripsi: RF DIR COUPLER 6GHZ-18GHZ 6TDFN Persediaan: 3016 pcs RFQ</p> |
| <p>MACP-010250-C808A0 Produsen: Aeroflex (MACOM Technology Solutions) Deskripsi: RF DIR COUPLER 5MHZ-1.2GHZ MOD Persediaan: 114443 pcs RFQ</p> | <p>MACP-010562-001SMB Produsen: Aeroflex (MACOM Technology Solutions) Deskripsi: EVAL BOARD FOR MACP-010562-TR100 Persediaan: 5017 pcs RFQ</p> |
| <p>MACP-010561-001SMB Produsen: Aeroflex (MACOM Technology Solutions) Deskripsi: EVAL BOARD FOR MACP-010561-TR100 Persediaan: 3678 pcs RFQ</p> | <p>MACP-010561-000000 Produsen: Aeroflex (MACOM Technology Solutions) Deskripsi: RF DIR COUPLER 2GHZ-6GHZ 6TDFN Persediaan: 4788 pcs RFQ</p> |

